

Miller Exhaust Corrected.txt

FLOW PRO Report

Test Name

Miller Ex 865 Triumph

Lift	CCFM
-----	-----
0.0250	14.4
0.0500	31.2
0.0755	47.4
0.1000	70.3
0.1250	90.5
0.1500	112.0
0.1750	125.4
0.2000	136.8
0.2250	147.1
0.2500	156.4
0.2750	163.3
0.3000	168.9
0.3250	173.1
0.3500	176.5
0.3750	178.9
0.4000	181.9
0.4250	184.3
0.4500	186.6

Test Conducted through 2.00" long exhaust spigot.
Tested at 28" H2O

FLOW PRO Report

Test Name

BoMiller Intake Triumph 865

Lift

CCFM

0.0250	17.8
0.0500	37.0
0.0750	57.0
0.1000	76.4
0.1250	99.3
0.1500	118.2
0.1750	135.4
0.2000	152.2
0.2250	168.3
0.2500	181.4
0.2750	192.6
0.3000	201.0
0.3250	206.0
0.3505	208.2
0.3750	209.5
0.4000	210.1
0.4250	210.8
0.4500	211.1

Head was tested through manifold, carb, and airfilter.
Test Pressure 28" H2O